


Note 1. ※1: Prepared holes for M4 tapping screw



- 1 Evaporator air inlet connection - for return duct
- 2 Evaporator air outlet connection - for supply duct
- 3 Liquid pipe connection (No. 1) ϕ 12.7
- 4 Gas pipe connection (No. 1) ϕ 25.4
- 5 Liquid pipe connection (No. 2) ϕ 12.7
- 6 Gas pipe connection (No. 2) ϕ 25.4
- 7 Drain pipe connection FPS1B
- 8 Earth terminal M5
- 9 Power supply intake ϕ 27 Hole
- 10 The holes for anchor bolts 4- ϕ 15 holes (for M12)